

Leica mojoXact Plus Universal Terminal Release notes

Public Release Notes

Version 2.1.134

- when it has to be **right**



Table of contents

1	Introduction	3
2	New functionality & key changes	4
2.1	JD R series: Security Dropouts	6
2.2	Glide Only Steering Aggressively	6
2.3	Client, Farm, Field Structure	7
2.4	Set A+ heading from current vehicle heading	8
2.5	Addition of Replay Guidance pattern for UT interface	8
2.6	Addition of AB Contour pattern for UT interface	9
2.7	Universal Terminal Screen updated	10

1 Introduction

General information

Leica Geosystems provides free of charge software updates for the Leica mojoXact Plus in order to provide customers with the best possible experience. This document describes the changes in the latest software release, how to use the new functionality and the various methods to upgrade the software.



There are three versions of this document which are intended for different audiences:

- **Public release notes**, intended for customers and a general audience.
 - **Dealer release notes**, intended only for dealers and provide additional information regarding dealer specific processes or support.
 - **Internal release notes**, intended for Leica Geosystems employees only. This version of the release notes are company confidential and includes general information, dealer information and additional details of all changes made to the software. This document should not be distributed to non Leica personnel.
-

Current Version

- Leica mojoXact Plus version **2.1.134**
 - Released March 2016.
-

Compatibility

This software is compatible with all mojoXact Plus connected to a Universal Terminal.

Leica mojoXact Plus – Public Release Notes

2 New functionality & key changes

Overview

- JD R series random security not satisfied error resolved (**v2.1.134**).
 - Glide Only steering aggressively issue resolved (**v2.1.134**).
 - Client, Farm, field structure has been added (v2.1.114).
 - Set A+ heading from current vehicle heading (v2.1.114).
 - Addition of Replay Guidance pattern for UT Interface (v2.1.114).
 - Addition of AB Contour pattern for UT Interface (v2.1.114).
 - Remove negative length entries (v2.1.114).
 - John Deere Sugarcane harvester support (v2.1.114).
 - Automatic terrain updates (v2.1.114).
 - Update the UT Guidance Screen (v2.1.114).
-

-
- New languages for UT Interface (v2.1.114).
 - Italian.
 - Czech (ISO 8859-1 and ISO 8859-15 characters).
 - Hungarian (ISO 8859-1 and ISO 8859-15 characters).
 - Universal Terminal Support Bug Fixes (v2.1.114).
 - Virtual Terminal CAN Dropouts in Fendt and MF fixed. Virtual Terminal issues on JD R Series vehicles fixed (v2.0.298).
 - ES Plus performance improvements (v2.0.298).
 - SteerDirect ES Plus Support (v2.0.258).
 - Universal Terminal support (v2.0.258).
-

2.1 JD R series: Security Dropouts

Overview

This was a known issue with the mojoXact Plus running UT software. Periodically CAN messages are lost. The issue is fixed with the new version.

2.2 Glide Only Steering Aggressively


Overview

Autosteer did not work properly using GLIDE Only corrections. The issue is fixed with the new version.

2.3 Client, Farm, Field Structure.

Overview

- The user can create new Clients, farms and fields.
- The user can move Farms, Fields and waylines from field management screen.
- The user can edit Clients, farms and fields.
- Waylines can be saved under Client, Farm, Field Structure. Waylines can be moved and edited.



2.4 Set A+ heading from current vehicle heading.

Overview

- User will be able to set the A+ using the current heading. Of this way, the user doesn't need to know the heading to mark a wayline.
-

2.5 Addition of Replay Guidance pattern for UT Interface.

Overview

- Now, Replay Guidance option is available on Universal Terminal Solution.
 - Shape files can be imported.
-

2.6 Addition of AB Contour pattern for UT Interface.


Overview

- Now, AB Contour Guidance option is available on Universal Terminal Solution.
 - Nudge function is available for AB contour.
 - In AB Contour is possible Record and Pause option.
-

2.7 Universal Terminal Screen updated

Overview

- The main Guidance screen has been updated. Different options have been added.



Leica Geosystems AG
Heinrich-Wild-Strasse
CH-9435 Heerbrugg
Switzerland
Phone: +41 71 727 31 31
www.leica-geosystems.com

- when it has to be **right**

Leica
Geosystems

**Leica moJoXact Plus – Public Release Notes –
v2.1.134**
Original text
© 2010 Leica Geosystems AC, Heerbrugg, Switzerland